


# Torque Tester




## ZV011 new

### Specifications:

 7.7  /  1 / 1

Calibration range	2~60 Nm
Accuracy	±0.5%
Units of measurement	Lb-in, Lb-ft, Kg-m, Kg-cm, N-m, N-cm
Input Hex A/F (mm)	10mm
Square Drive Adaptor (inch)	1/4", 3/8", 1/2"
Operating Temperature Range	+5°C~ +40°C
Storage Temperature Range	+0°C~ +70°C
AC Power Input	100-240VAC 50/60HZ
Base material/ Finish	Aluminum Alloy / Painting
Dimension	210(L) x 150(W) x 140(H) mm



ZV011A		Europe
ZV011B		America & Asia
ZV011D		Australia & New Zealand




## ZV012 new

### Specifications:

 8.1  /  1 / 1

Calibration range	8~400 Nm
Accuracy	±0.5%
Units of measurement	Lb-in, Lb-ft, Kg-m, Kg-cm, N-m, N-cm
Input Hex A/F (mm)	22mm
Square Drive Adaptor (inch)	3/8", 1/2", 3/4"
Operating Temperature Range	+5°C~ +40°C
Storage Temperature Range	+0°C~ +70°C
AC Power Input	100-240VAC 50/60HZ
Base material/ Finish	Aluminum Alloy / Painting
Dimension	210(L) x 150(W) x 140(H) mm




ZV012A		Europe
ZV012B		America & Asia
ZV012D		Australia & New Zealand




## ZV013 new

### Specifications:

 8.9  /  1 / 1

Calibration range	100~1500 Nm
Accuracy	±0.5%
Units of measurement	Lb-in, Lb-ft, Kg-m, Kg-cm, N-m
Input Hex A/F (mm)	36mm
Square Drive Adaptor (inch)	3/4"
Operating Temperature Range	+5°C~ +40°C
Storage Temperature Range	+0°C~ +70°C
AC Power Input	100-240VAC 50/60HZ
Base material/ Finish	Aluminum Alloy / Painting
Dimension	210(L) x 150(W) x 140(H) mm



ZV013A		Europe
ZV013B		America & Asia
ZV013D		Australia & New Zealand

