



# Verification of Conformity

*Of Test Report No.: GO15031302B*

**Applicant :** King Tony Tools Co., Ltd.

**Address :** **No. 11, Alley 150, Lane 516, Hsi Nan Rd. Sec. 2, Wu-Jih Dist., Taichung City 41467, Taiwan (R.O.C.)**

**Product :** LED Working Light

**Model Designation :** HL-9018, 79832

**Series Description :** N/A

A sample of the equipment has been tested for CE marking according to the Photobiological Safety of Lamps and Lamp Systems. Standard(s) used for showing compliance with essential requirements of the directive.

**Standard :** EN 62471:2008: Photobiological Safety of Lamps and Lamp Systems

The referred test report(s) show that the product fulfills the requirements in the Photobiological Safety of Lamps and Lamp Systems for CE marking. On the basis, together with the manufacturer's own documented production control, the manufacturer ( or his European authorized representative ) can in his EC Declaration of Conformity verify with the EC Photobiological Safety of Lamps and Lamp Systems.

This verification shall be accompanied with test report.



**Approved by :** \_\_\_\_\_ **Managing Director**

**Issued Date :** April 10, 2015

**Test site: Great One Global Certification Co., Ltd.**  
**9F-2, No. 120, Qiaohe Rd., Zhonghe Dist., New Taipei City 235, Taiwan (R.O.C.)**  
**Tel: +886-2-2248-0810 Fax: +886-2-2248-0811**